




State of Utah
DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

Michael O. Leavitt
Governor
Kathleen Clarke
Executive Director
Lowell P. Braxton
Division Director

1594 West North Temple, Suite 1210
PO Box 145801
Salt Lake City, Utah 84114-5801
801-538-5340
801-359-3940 (Fax)
801-538-7223 (TDD)

July 25, 2001

TO: Minerals File

FROM: Tom Munson, Senior Reclamation Specialist 

RE: Site Inspection, Terra Resources, Inc., Southern White/Mountain Rose Project, S/001/047, Beaver County, Utah

Date of Inspection: June 19, 2001
Time of Inspection: 6:50 p.m.
Conditions:
Participants: Sheri Wysong, BLM; Tom Munson, DOGM

Purpose of Inspection: To visit the site while in the area

I visited the new red marble quarry, there is a road going into a red marble quarry and a small stockpile pad area that has nothing on it now.

I GPS'd the pit, the small pad area and the road. The road was done in three segments, to a fence line that appears to be the property boundary.

There is another quarry that I can see, but it looks like an older quarry at the very top at the end of the road, so I'm not sure they have done anything at that quarry yet. I will have to check with Mr. Sagers regarding this quarry. I GPS'd the disturbance associated with the road and the red marble pit and loading area.


jb
cc: Jeff Sagers, Terra Resources
S01-47-ins.doc

0001

Southern White/Mountain Rose

Terra Resources Inc.

S/001/047



0.06 0 0.06 0.12 Miles

■ Disturbed area-pits

~ Road



SOUTHERN WHITE / MOUNTAIN ROSE



P0002273.JPG
06/19/1901



P0002269.JPG
06/19/1901



P0002270.JPG
06/19/1901

S/001/047



P0002271.JPG
06/19/1901



P0002272.JPG
06/19/1901